

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Front exterior

Photo Number
1



Description:
Front and right
side exterior

Photo Number
2

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Right side exterior

Photo Number
3



Description:
Back exterior

Photo Number
4

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Granite floor
support pier

Photo Number
5



Description:
Granite floor
support pier, no
longer in contact
with timber floor
framing

Photo Number
6

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Concrete floor
support pier

Photo Number
7



Description:
Stacked wood
blocking in contact
with dirt floor
below bathroom
area

Photo Number
8

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Clearance between
first floor framing
and crawl space
floor

Photo Number
9



Description:
Clearance between
floor support
framing and crawl
space floor

Photo Number
10

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Clearance between
first floor framing
and crawl space
floor

Photo Number

11



Description:
Clearance between
first floor framing
and crawl space
floor

Photo Number

12

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Standing water in
Water Street ditch
at front of building

Photo Number
13



Description:
Blocked riser pipe
at exterior front
right of foundation

Photo Number
14

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Single header (in background) supporting long floor joists at front left of building

Photo Number

15



Description:
Light duty single joist header, original floor joists (left) and light duty floor framing (right)

Photo Number

16

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Light duty floor
framing at front
left of crawl space

Photo Number
17



Description:
Light duty floor
framing at front
left of crawl space

Photo Number
18

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
File cabinets at
front left of
building

Photo Number
19



Description:
Floor surface
below file cabinets
at front left

Photo Number
20

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Rot at back sill

Photo Number
21



Description:
Rot at back sill

Photo Number
22

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Rot at back sill

Photo Number
23



Description:
Rotted rim joist
and floor joists,
back left

Photo Number
24

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Rotted band joist,
back left

Photo Number
25



Description:
Rotted rim joist

Photo Number
26

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Mold on rotted rim
joist, back right

Photo Number
27



Description:
Rotted rim joist
and floor joist,
back right

Photo Number
28

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Mold growth and deterioration at along back portion of right side wall

Photo Number
29





Description:
Rotted stud at back right of building

Photo Number
30

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Back exterior door

Photo Number
33



Description:
Abraded paint at
location where
door rubs frame

Photo Number
34

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Roof framing

Photo Number
35



Description:
Roof framing

Photo Number
36

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Roof framing

Photo Number
37



Description:
Back entrance
ramp and canopy

Photo Number
38

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Support pier at
back entrance

Photo Number
39



Description:
Steps at back
entrance

Photo Number
40

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Second floor
egress staircase
and landing

Photo Number
41



Description:
Angle support
braces at second
floor egress
staircase and
landing

Photo Number
42

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Nov. 13, 2014



Description:
Support ledger at
right side staircase
and landing

Photo Number
43



Description:
Support ledger at
right side staircase
and landing

Photo Number
44