

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Openings created
for invasive
inspection

Photo Number
46



Description:
Wet insulation and
rotted siding

Photo Number
47

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Rot damage on
stud and wall
sheathing

Photo Number
48



Description:
Rot damage on
stud and wall
sheathing

Photo Number
49

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Rot damage on
stud and wall
sheathing

Photo Number
50



Description:
Rotted stud and
wall sheathing 80
inches from front
of right rear
window

Photo Number
51

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Rotted stud, sill framing and wall sheathing (note that fire stop has disintegrated entirely)

Photo Number
52



Description:
Wall opening in front right stairwell

Photo Number
53

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Stud and wall
sheathing in front
right stairwell

Photo Number
54



Description:
Second floor joist,
second floor deck
above right side
wall

Photo Number
55

Location:
Addison Town Hall
Addison, Maine

Photo Taken by:
Keith R Brown, P.E.

Date:
Feb. 6, 2015



Description:
Second floor joist-
to-stud connection

Photo Number

56



Description:
Second floor joist,
second floor deck
above right side
wall

Photo Number

57